

ASSIGNMENT-I

SUB: MICROPROCESSOR AND ITS APPLICATION.

SEM-EE 6TH

Q.1 :Draw the timing Diagram of i) STA3000 ii) MVI B,20

Q.2: DETERMINE THE SIZE OF INSTRUCTION i) LXI B,7898H ii) ADD B iii) MOV B,C iv)SBI C,10